

STERAMIST[®] AIR FORCE BASE COVID-19 RESPONSE

OVERVIEW:

When a San Antonio-based Air Force base had begun to suspect possible coronavirus contamination on the premises, authorities needed to locate a technology and service quick enough to complete the job quickly and efficiently. As a response, relevant military staff reached out to local TSNTM member Wow Total Cleaning & Restoration to tackle the challenge by utilizing SteraMist ionized Hydrogen Peroxide (iHPTM) in the potentially affected areas.



SCOPE OF WORK:

Two (2) facilities on the base required disinfection - the Community Center and Equipment Maintenance Building. An 18-hour turnaround deadline was requested. Four (4) on-site SteraMist technicians were assigned to the job to ensure that the goal was reached.

MEETING THE NEED:

In order to address the issue, all four (4) technicians proceeded to treat the area. Treated surfaces include high-touch areas, such as doors, handles, trash bins, switches, kitchen areas, drawers and cabinets, dispensers, and bathroom areas. 5 gallons of solution were used to treat both facilities.



THE RESULT:

Having used only a SteraMist Surface Unit, a SteraMist Environment Unit, five gallons of solution, and four on-site technicians, the two-facility job was completed in 10 hours - well under the given 18 hour deadline. Each high-touch area was thoroughly disinfected.